

TOWN of MAY
WASHINGTON COUNTY, MINNESOTA
OFFICIAL TOWN BOARD MINUTES
SPRING ROAD TOUR
April 30, 2020

The Board of Supervisors of the Town of May convened the Spring Road Tour on Thursday, April 30, 2020 at the Town Hall parking lot at 9:00 a.m. and ended at 12:30 p.m. Those present included: Board members John Adams and Bill Voedisch; Clerk/Treasurer Linda Tibbetts; and Town Engineer Katie Koscielak.


Key Highlights of Road Notations:

- 122nd Street
 - Fill four potholes
- 125th Street
 - Fill potholes
- 124th Street
 - Shore up bituminous curbing near 95
- 127th Street
 - Missing one of three culverts – need to find location; culvert near 14010 is half filled with dirt.
- 130th Street
 - Dig out culvert and clean; fill new potholes; crack seal and chip seal
- 130th Street Lane North
 - Dig out culvert and clean
- 142nd Street
 - Big cracks need filling in cul-de-sac
- Northbrook Avenue North
 - Culvert not on map
- Oldfield Road
 - Replace culvert with longer one
 - Washout near bituminous to gravel
- Ozark Avenue North
 - Fix collapsing storm drains

- Panorama Avenue
 - Fill large/wide crack
- Parade Avenue
 - Bad condition - Fill potholes
- Paragon Avenue
 - Bad condition – Fill potholes
- Paris Avenue
 - Bad condition – Fill potholes. Fix swale
- Partridge Court
 - Cut out and fill bad areas
- Quail Avenue
 - Need new RR crossing sign and placement


See attached spreadsheet of road notations.

Attest,




 Linda Tibbetts
 Clerk/Treasurer

Respectfully submitted,



 Bill Voedisch
 Board Chair



Road Tour Findings

Road Name	G/B	Fall 2019 Findings	Spring 2020 Findings	From	To
120th Street N	G	Good condition	Not inspected	Norell Avenue N (CR 55)	Ochipwe Avenue N (CR 11)
120th Street N	G	Need to mark culvert(s); road in good condition after spring flood. No need for gravel.	Not inspected	Myeron Road N (CR 61)	Norell Avenue N (CR 55)
121st Street N	G/B	Good condition. Blowout was fixed this fall. Future blowouts expected/alligator. Candidate for crack seal	Candidate for chip seal	Manning Trail N (CR 15)	Cul-De-Sac (west)
122nd Street N	B	Bad shape. Good candidate for reclaim.	Fill potholes	Partridge Road (CR 51)	West End
124th Street N	B	Good condition. crack seal needed at Cul-de-sac	Fill potholes	Manning Trail N (CR 15)	Lockridge Avenue N
124th Street N	B	Excellent condition. We need to shore up the curb near 95 so it doesn't collapse. Also, need to inform Dresel Plow Drivers about the curbing.	Great condition. Shore up curb near 95.	St. Croix Trail (TH 95)	Queens Way N / Quail Way N
124th Street N	B	Good condition	Candidate for crack seal	St. Croix Trail (TH 95)	Ravine Circle N
126th Street N	B	Good condition. Crack down the middle of road. crack seal potential	Candidate for crack seal	Lockridge Avenue N	May Avenue N
127th Street N	B	Good condition. Needs crack seal.	Need to find missing culvert; one buried near 14010/filled with dirt	Otchipwe Avenue N (CR 11)	Cul-De-Sac (west)
130th Street N	G	Good	Not inspected	Keystone Avenue N (CR 57)	Southeast End
130th Street N	G	Good Condition. Sides good.	Not inspected	Lynch Road N (CR 58)	West End
130th Street N	B	Excellent condition. crack seal needed.	Bad condition. Dig out culvert/clean. New potholes need filling. Needs crack seal and chip seal.	Partridge Road N (CR 51)	Panorama Avenue N
130th Street N	B	Needs help. Repave? Not a good candidate for mill and overlay	Bad condition.	Panorama Avenue N	Cul-De-Sac (west)
130th Street N	G	Good		130th Street N	Northeast End
130th Street Lane N	G	Excellent. Culvert plugged?	Culvert needs cleaning - half plugged.	130th Street N	130th Street N
131st Street / Parade Ave	B	Excellent	No comments	Panorama Avenue N	Northeast End
131st Street N	G	Good. Needs gravel.	Not inspected	Otchipwe Avenue N (CR 11)	Cul-De-Sac (east)
133rd Street N	G	Okay. Carve out drain. Add gravel.	Not inspected	Partridge Road N (CR 51)	Northwest End (Private Road)
135th Street N	G	Okay. Add gravel	Not inspected	Square Lake Trail N (CR 7)	Oldfield Road N
136th Street N	G	Not inspected due to snow	Not inspected	Oldfield Road N	Cul-de-sac (east)
136th Street N	G	Okay. Needs grading. Culvert okay.	Not inspected	Partridge Road North (Co. Rd. 51)	East to Dead End
140th Street N	G	Not inspected due to snow	Not inspected	Lynch Road N (CR 58)	East End

Road Tour Findings

Road Name	G/B	Fall 2019 Findings	Spring 2020 Findings	From	To
142nd Street N	B	Good condition	Candidate for crack seal.	Manning Trail N (CR 15)	Cul-De-Sac (west)
144th Street N	G	Not inspected due to snow	Not inspected	St. Croix Trail (TH 95)	Racine Avenue N
148th Street N	B	Good condition	Not inspected	Manning Trail N (CR 15)	Cul-De-Sac (west)
148th Street N	G	Not inspected due to snow	Not inspected	Manning Trail N (CR 15)	Manning Court N
150th Street N	G	Not inspected due to snow	Not inspected	St. Croix Trail (TH 95)	West End
150th Street N	G	Not inspected due to snow	Not inspected	May Avenue N	Norell Avenue N (CR 55)
152nd Street N	G	Not inspected due to snow	Not inspected	St. Croix Trail (TH 95)	East to Dead End
154th Street N	G	Not inspected due to snow	Not inspected	St. Croix Trail (TH 95)	West to Dead End
155th Street N	G	Not inspected due to snow	Not inspected	Manning Trail N (CR 15)	May Avenue N
165th Street N	G	Not inspected due to snow	Not inspected	May Avenue N	West End
169th Street N	G	Not inspected due to snow	Not inspected	Kirby Avenue N	Kimbro Avenue N
175th Street N	G	Not inspected due to snow; low hanging tree needs removal.	Not inspected	Ostrum Trail N (CR 4)	West End
176th Street N	G	Not inspected due to snow	Not inspected	Manning Trail N (CR 15)	Cul-De-Sac (west)
177th Street N	G	Not inspected due to snow	Not inspected	May Avenue N	Olinda Trail N (CR 3)
177th Street N	G	Not inspected due to snow	Not inspected	May Avenue N	Ostrum Trail North (CSAH 4)
180th Street N	G	Not inspected due to snow	Not inspected	Keystone Avenue N	Manning Trail N (CR 15)
180th Street N	G	Not inspected due to snow	Not inspected	Manning Trail N (CR 15)	Vets Camp Entrance
Arcola Trail N	G/B	Grave Good / Bituminous Great	Not inspected	St. Croix Trail (TH 95)	South Township Limits
Johnson Road	B	Okay condition. Roundup for weeds.	Candidate for crack seal/chip seal	St. Croix Trail (TH 95)	Gravel Surface
Keystone Avenue N	G	Not inspected due to snow	Not inspected	170th Street N (CR 4)	180th Street N
Kimbro Avenue N	G	Not inspected due to snow	Not inspected	169th Street N	170th Street N (CR 4)
Kirby Avenue N	G	Not inspected due to snow	Not inspected	170th Street N (CR 4)	169th Street N
Kirby Avenue N	G	Not inspected due to snow	Not inspected	Lynch Road N (CR 58)	Cul-De-Sac (north)
Lockridge Avenue N	B	Good condition. Crack down middle of road.	Not inspected	124th Street N	126th Street N
Lomond Trail N	G	Not inspected due to snow	Not inspected	May Avenue N	Big Marine Lake
Lynch Road N	B	Good.	Not inspected	Keystone Avenue N (CR 57)	Manning Trail N (CR 15)
Madson Road	G	Bad shape. Needs edging for draining. Needs help.	Not inspected	Square Lake Trail N (CR 59)	South End
Manning Court N	G	Not inspected due to snow	Not inspected	148th Street N	Cul-De-Sac (north)
Margo Avenue N	G	Not inspected due to snow	Not inspected	Lamond Trail N	North Township Limits
May Avenue N	G	Not inspected due to snow	Not inspected	120th Street N (CR 61)	Conc. RR Bridge (136' x 32')
May Avenue N	G	Not inspected due to snow	Not inspected	Conc. RR Bridge (136' x 32')	Square Lake Trail N (CR 7)

Road Tour Findings

Road Name	G/B	Fall 2019 Findings	Spring 2020 Findings	From	To
May Avenue N	B	Good condition. Consider reclaiming to gravel in the future	Candidate for reclaiming to gravel	Square Lake Trail N (CR 7)	Soo Line RR Crossing
May Avenue N	G	Not inspected due to snow	Not inspected	Soo Line RR Crossing	155th Street N
May Avenue N	G	Not inspected due to snow	Not inspected	155th Street N	170th Street N (CR 4)
May Avenue N	G	Not inspected due to snow	Not inspected	170th Street N (CR 4)	177th Street N
Moonlight Bay	B	Good	Good condition	Square Lake Trail N (CR 7)	South End ("Y")
Morgan Avenue N	G	Not inspected due to snow	Not inspected	Morris Trail N	North End
Morgan Avenue N	B	Pudding at 150th and Morgan; farm land flooding on north end; sides at corner need to be carved out, culvert installed; swale is too high; road has transverse cracking; crack seal candidate; great shape; recently fogged sealed.	Not inspected	150th Street N	Cul-De-Sac (south)
Morris Trail N	G	Not inspected due to snow	Not inspected	May Avenue N	Norell Avenue (CR 55)
Nason Hill Road N	G	Not inspected due to snow	Not inspected	Orwell Road North	Paul Avenue N (CR 7)
Norell Avenue Court	B	Good condition	Candidate for chip seal	Norell Avenue N (CR 55)	Cul-De-Sac (east)
Norell Avenue N	B	Not inspected due to snow	Not inspected	177th Street N	182nd Street N
Northbrook Avenue N	B	Not inspected due to snow	Culvert not on map. Candidate for crack seal.	Square Lake Trail N (CR 7)	Cul-De-Sac (southeast)
Northridge Avenue N	B	Good condition. Cracking. 25 years old. Need patching and cutouts done.	Not inspected	170th Street N (CR 4)	Cul-De-Sac (south)
Oldfield Road N	G/B	Excellent	G-Not inspected B-okay shape	Norell Avenue N (CR 55)	Ostlund Trail N
Oldfield Road N	G/B	Good. Culvert repair needed ASAP.	Replace culvert with longer one.	Ostlund Trail N	Square Lake Trail N (CR 7)
Oldfield Road N	G	Bad shape. Needs gravel.	Not inspected	135th Street N	Square Lake Trail N (CR 7)
Old Guslander Trail N	G	Not inspected due to snow	Not inspected	Ostrum Trail N (CR 4)	East Township Limits
Orwell Road North	G	Not inspected due to snow	Not inspected	170th Street N (CR 4)	Nason Hill Road N
Ostlund Court North	B	Excellent.	Excellent	Ostlund Trail North	Cul-de-Sac (east)
Ostlund Trail North	G/B	Gravel Good. Bituminous BAD.	Candidate for reclaiming to gravel	Oldfield Road N	Paul Avenue N (CR 7)
Ozark Avenue N	B	Okay. Candidate for mill and overlay in 3-5 years. Fix drain.	Fix storm drains - collapsing	Square Lake Trail N (CR 7)	Cul-de-Sac (north)
Ozark Court	B	Good.	Candidate for chip seal	Ozark Ave.	cul-de-sac
Ozark Trail N	G/B	Gravel Good. Bituminous okay.	Not inspected	Otchipwe Avenue N (CR 11)	North End

Road Tour Findings

Road Name	G/B	Fall 2019 Findings	Spring 2020 Findings	From	To
Panorama Avenue N	G/B	Gravel okay. Bituminous good.	Large wide crack needs sealing	130th Street N	North End (Private Road)
Parade Avenue N	B	Okay. Back end bad.	Bad condition - fill potholes	122nd Street N	Cul-De-Sac (west)
Parade Avenue N	G	Not inspected due to snow.	Not inspected	Ostrum Trail N (CR 4)	North Township Limits
Paragon Avenue N	B	Not inspected due to snow	Bad condition - fill potholes	Square Lake Trail N (CR 7)	Cul-De-Sac (south)
Paris Avenue N	B	Bad. Many blowouts. Reclaim?	Bad condition - fill potholes. Fix swale	122nd Street N	Cul-De-Sac (southwest)
Paris Avenue N	G	Bad shape.	Not inspected	Square Lake Trail N (CR 7)	Northwest End
Partridge Court N	B	Okay. Keep an eye on it. Potential mill and overlay.	Cut out bad areas. Candidate for crack seal	Partridge Road N (CR 51)	Cul-De-Sac (southwest)
Paul Court N	B	Good condition. Potential candidate for crack seal. Road breaking up at Cul-de-sac.	Good condition	Nason Hill Road N (CR 7)	Cul-De-Sac (north)
Quail Ave/Quail Ave	B	Okay. NEEDS NEW SIGNS for RR Crossing.	Candidate for crack seal; needs new signs	RR Crossing	RR Crossing
Queens Way/Quail Ave	B	Okay. Keep an eye on it. crack seal needed.	Candidate for chip seal	124th Street N	124th Street N
Racine Avenue N	G	Okay.	Not inspected	144th Street N	Cul-De-Sac (north)
Ravine Circle N	B	Good.	Candidate for mill and overlay	124th Street N	124th Street N
Riverview Trail N	B	Good. Potential crack seal. Fix pothole on corner.	Candidate for crack seal	St. Croix Trail (TH 95)	Cul-De-Sal (south)
Square Lake Trail Court	B	Excellent	Not inspected	Square Lake Trail N (CR 7)	Cul-De-Sac (northeast)